

# FATALITY NARRATIVE

# **Pesticide Handler Run Over by Tractor**

**Industry: Farm supplies merchant wholesalers** Task: Attempting to access cab of moving tractor **Occupation: Pesticide handler** 

Type of Incident: Tractor-related/run over

Incident Date: October 15, 2013 Release Date: June 3, 2014 SHARP Report No.: 71-131-2014 Case No.: 13WA03701

On October 15, 2013, a 34-year-old agricultural pesticide handler died when he was run over by a tractor. On the day of the incident, there were two workers employed by different employers who were working to apply a soil fumigant pesticide to a field. One worker was a certified pesticide handler (victim) whose task was to load the fumigant from stationary field tanks into trailermounted tanks being pulled by tractors. He had been at this site for about a week. The other worker was a tractor operator/pesticide applicator who was operating a tracked tractor pulling a 1,600-gallon trailer-mounted pesticide tank to fumigate his employer's fields. The two workers started work at 1:30 p.m. and were scheduled to work to 11:30 that evening. At about 7:20, the victim exited his parked pickup truck on the edge of a field and walked toward the tractor, which was actively applying fumigant. He did not communicate with the operator. As it was dark and the victim was not wearing a high visibility vest, the tractor operator did not see the victim approaching the moving tractor until he was a short distance away. He began to slow the tractor from about 5.5 mph to 5 mph. The victim approached the tractor's left side and reached for the cab access ladder handrail and



The victim was attempting to climb the tractor cab access ladder when he was run over by the moving left rear track.

attempted to place his left foot on the ladder's bottom step. As he was attempting to mount the ladder of the moving tractor, his right leg was caught by the left rear track and he was pulled under and run over by the track. Investigators determined that the victim had previously ridden along with the operator, but he had entered the operator's cab only when the tractor was stationary after the victim had refilled the tractor's pesticide tank. The tractor operator's manual stated that the extra seat in the cab is to be used only for instructional and service diagnosing purposes.

Please help us improve FACE publications by taking a 1-minute survey at WA FACE survey.com

Statewide Statistics: This was number 39 of 52 work-related fatalities in Washington State during 2013, and was number 5 of 6 agriculture-related fatalities.

This narrative was developed to alert employers and employees of a tragic loss of life of a worker in Washington State and is based on preliminary data ONLY and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

Developed by WA State Fatality Assessment and Control Evaluation (FACE) Program and the Division of Occupational Safety and Health (DOSH), WA State Dept. of Labor & Industries. The FACE Program is supported in part by a grant from the National Institute for Occupational Safety and Health (NIOSH grant# 5 U60 OH008487-09). For more information, contact the Safety and Health Assessment and Research for Prevention (SHARP) Program. 1-888-667-4277.

## Requirements

#### **Employers must:**

- Provide employee safety education and training programs which include information about tractor and other agricultural equipment hazards and safe work practices.
  - See WAC 296-307-018(6).
- Develop a written accident prevention program tailored to the needs of your agricultural operation and to the types of hazards involved. See WAC 296-307-030(2).
- The manufacturer's instruction manual must be the source of information for the safe operation of field equipment. See WAC296-307-076(2).

### Recommendations

- Never attempt to get on a moving tractor or other agricultural equipment.
- Do not ride along with equipment operators unless there is an operational need, such as operator training or service diagnosing.
- Establish and use methods of communication with equipment operators when approaching equipment or working in the vicinity.



