

# Lockout/Tagout (Control of Hazardous Energy)

Chapter 296-803 WAC

## Statutory Authority

### 296-803-100 Scope.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-100, filed 07/20/04, effective 11/01/04.]

### 296-803-200 Energy Control Program.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-200, filed 07/20/04, effective 11/01/04.]

### 296-803-20005 Establish a written energy control program.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-20005, filed 07/20/04, effective 11/01/04.]

### 296-803-300 Machine Design and Construction.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-300, filed 07/20/04, effective 11/01/04.]

### 296-803-30005 Make sure new or modified machines and equipment can accept lockout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-30005, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-30005, filed 07/20/04, effective 11/01/04.]

### 296-803-400 Energy Control Devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-400, filed 07/20/04, effective 11/01/04.]

### 296-803-40005 Provide appropriate means to control energy.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-40005, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40005, filed 07/20/04, effective 11/01/04.]

<http://www.lni.wa.gov/>

# Lockout/Tagout (Control of Hazardous Energy)

Chapter 296-803 WAC

## Statutory Authority

296-803-40010 Make sure lockout and tagout devices meet these requirements.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40010, filed 07/20/04, effective 11/01/04.]

296-803-40015 Make sure lockout devices meet these additional requirements.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40015, filed 07/20/04, effective 11/01/04.]

296-803-40020 Make sure tagout devices meet these additional requirements.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-40020, filed 07/20/04, effective 11/01/04.]

296-803-500 Energy Control Procedures.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-500, filed 07/20/04, effective 11/01/04.]

296-803-50005 Use energy control procedures.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50005, filed 07/20/04, effective 11/01/04.]

296-803-50010 Meet these requirements when applying lockout or tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-50010, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50010, filed 07/20/04, effective 11/01/04.]

# Lockout/Tagout (Control of Hazardous Energy)

Chapter 296-803 WAC

## Statutory Authority

296-803-50015 Meet these additional requirements when applying lockout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50015, filed 07/20/04, effective 11/01/04.]

296-803-50020 Meet these additional requirements when applying tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50020, filed 07/20/04, effective 11/01/04.]

296-803-50025 Protect employees from the hazards of stored and residual energy.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50025, filed 07/20/04, effective 11/01/04.]

296-803-50030 Verify that the machine or equipment is safe before starting work.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50030, filed 07/20/04, effective 11/01/04.]

296-803-50035 Meet these requirements when removing lockout or tagout devices and energizing the machine or equipment.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50035, filed 07/20/04, effective 11/01/04.]

296-803-50040 Meet these requirements if it's necessary to temporarily energize a machine, equipment, or component for testig or positioning.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50040, filed 07/20/04, effective 11/01/04.]

<http://www.lni.wa.gov/>

# Lockout/Tagout (Control of Hazardous Energy)

Chapter 296-803 WAC

## Statutory Authority

296-803-50045 Protect employees during shift or personnel changes.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50045, filed 07/20/04, effective 11/01/04.]

296-803-50050 Protect employees working in a group.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50050, filed 07/20/04, effective 11/01/04.]

296-803-50055 Meet these additional requirements if more than one group is used.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50055, filed 07/20/04, effective 11/01/04.]

296-803-50060 Coordinate with outside employers servicing or maintaining your machines or equipment.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-50060, filed 07/20/04, effective 11/01/04.]

296-803-600 Training.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-600, filed 07/20/04, effective 11/01/04.]

296-803-60005 Provide and document employee training on the energy control program.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-60005, filed 07/20/04, effective 11/01/04.]

296-803-60010 Provide additional training if you use tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-60010, filed 07/20/04, effective 11/01/04.]

# Lockout/Tagout (Control of Hazardous Energy)

Chapter 296-803 WAC

## Statutory Authority

296-803-60015 Retrain employees when necessary.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-60015, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-60015, filed 07/20/04, effective 11/01/04.]

296-803-700 Periodic Reviews.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-700, filed 07/20/04, effective 11/01/04.]

296-803-70005 Perform and document periodic reviews to verify employees know and follow the energy control procedures.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-70005, filed 07/20/04, effective 11/01/04.]

296-803-70010 Do periodic reviews of procedures using lockout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-70010, filed 07/20/04, effective 11/01/04.]

296-803-70015 Do periodic reviews of procedures using tagout devices.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-70015, filed 07/20/04, effective 11/01/04.]

296-803-800 Definitions.

[Statutory Authority: RCW 49.17.010, .040, .050, and .060. 09-16-108 (Order 09-08), § 296-803-800, filed 08/04/09, effective 11/01/09. Statutory Authority: RCW 49.17.010, .040, .050, and .060. 04-15-105 (Order 03-12), § 296-803-800, filed 07/20/04, effective 11/01/04.]

<http://www.lni.wa.gov/>

# Notes

---

1 • 800 • 4BE SAFE (1 • 800 • 423 • 7233)